ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	12	Shettihalli
Street ID	**Street Name**	**Significant Landmark**
W0756	NA	Chikkasandra main road
Segment No.	**Total Length (m)**	
12/S-W0756/S013201	421.29	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	421.29	77.506400	13.064463	77.509931	13.064376	Chikkasandra main road	surrounding area

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads and asphalting to medarahalli area shettihalli main road, VA railway gate to Medarahalli main road and Chikkasancra area bone m	100	18-19
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to roads and asphalting to medarahalli area shettihalli main road, VA railway gate to Medarahalli main road and Chikkasancra area bone mill main road in ward no. 12	012-18-000017
Work Order No.	**Work Order Date**	**Period of Extention**
302/18-19.	02/02/2019	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
02/02/2019	05/02/2020	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M.S.VENKATESH		0.00
Phone No.	**E-Mail ID**	
9886066040		

Scanned by CamScanner

Field Inspection Details

Number of Trees	Any Other Information	Name
0		shivakumar
Date of Inspection	**Remarks**	
16/08/2021		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Scanned by CamScanner

Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	CE DAS	07/12/2021	15/09/2021	APPROVED
EE	EE DAS	27/08/2021	15/09/2021	COMPLETED
AEE	Kumarappa	24/08/2021	15/09/2021	Approved
AE	Shivakumar	16/08/2021	15/09/2021	provided
AE	Shivakumar	16/08/2021	15/09/2021	provided

Scanned by CamScanner

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	12	Shettihalli
Street ID	**Street Name**	**Significant Landmark**
W0262	Ambedkar Nagar Slum	Medarahalli main road
Segment No.	**Total Length (m)**	
12/S-W0262/S014647	438.70	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	438.70	77.510532	13.070440	77.507784	13.073205	Medarahalli	Shettihalli main road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads and Asphalting to Medarahalli area, Shettiyalli main road, Via railway main road, Chikkasandra bone mill main road in ward no.	1.5	18-19
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to roads and Asphalting to Medarahalli area, Shettiyalli main road, Via railway main road, Chikkasandra bone mill main road in ward no. 12	012-18-000017
Work Order No.	**Work Order Date**	**Period of Extention**
302/18-19..	02/02/2019	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
02/02/2019	05/02/2020	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M.S.venkatesh		0.00
Phone No.	**E-Mail ID**	
9886066040		

Scanned by CamScanner

Field Inspection Details

Number of Trees	Any Other Information	Name
0		shivakumar
Date of Inspection	**Remarks**	
16/08/2021		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Scanned by CamScanner

Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	CE DAS	07/12/2021	15/09/2021	APPROVED
EE	EE DAS	27/08/2021	15/09/2021	COMPLETED
AEE	Kumarappa H	24/08/2021	15/09/2021	approved
AE	Shivakumar	16/08/2021	15/09/2021	provided
AE	Shivakumar	16/08/2021	15/09/2021	provided

Scanned by CamScanner

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	12	Shettihalli
Street ID	**Street Name**	**Significant Landmark**
W0954	NA	Esky. Hospital road
Segment No.	**Total Length (m)**	
12/S-W0954/S021658	165.58	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	165.58	77.517422	13.061138	77.518842	13.061689	Shettihalli	Eskay hospital road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads and Asphalting to medarahali area , shettihalli main road, via railway gate to medarahalli main road, chikkasandra area, bonemil	1500	2018-19
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to roads and Asphalting to medarahali area , shettihalli main road, via railway gate to medarahalli main road, chikkasandra area, bonemill road in ward no. 12	012-18-000017
Work Order No.	**Work Order Date**	**Period of Extention**
302/18-19....	02/02/2019	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
02/02/2019	05/02/2020	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M.S.Venkatesh		0.00
Phone No.	**E-Mail ID**	
9886066040		

Scanned by CamScanner

Field Inspection Details

Number of Trees	Any Other Information	Name
0		shivakumar
Date of Inspection	**Remarks**	
16/08/2021		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Scanned by CamScanner

Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	CE DAS	07/12/2021	15/09/2021	Approved
EE	EE DAS	27/08/2021	15/09/2021	COMPLETED
AEE	Kumarappa H	24/08/2021	15/09/2021	approved
AE	Shivakumar	16/08/2021	15/09/2021	provided
AE	Shivakumar	16/08/2021	15/09/2021	provided

Scanned by CamScanner